

**ORFORD 217/112**  
NH 25A over BRACKETT BROOK

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Friday, November 09, 2018

SLAB AND APPROACH  
ROADWAY ASPHALT  
OVERLAY 2018.

A480 55



Friday, November 09, 2018

SMALL EROSION HOLES  
AROUND WEST APPROACH  
RAIL POSTS/ ROADWAY  
SHOULDER BEHIND SW  
WING.

A480 56



Friday, November 09, 2018

DOWNSTREAM PIER  
EXTENSION FOOTING  
EXPOSED UP TO 4 INCHES  
AT THE EXTENSION END;  
FILLED IN WITH GRAVEL AT  
THIS TIME.

A480 57



**ORFORD 217/112**  
NH 25A over BRACKETT BROOK

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Friday, November 09, 2018

SMALL VOIDS IN DRY LAID  
STONE AT DOWNSTREAM  
END OF NORTHEAST WING.

A480 58



Friday, November 09, 2018

WEST SPAN OPENING NOW  
5' 9", EAST SPAN OPENING  
6' 10" AT THE INLET END.

A480 59





**ORFORD 217/112**  
**NH 25A over BRACKETT BROOK**

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Monday, April 23, 2018

EXTENSIVE LEDGE AND RIP-  
RAP REPAIRS UPSTREAM  
FROM 2017 HEAVY RAIN  
EVENTS BY BOBM.

A466 24



Monday, April 23, 2018

EXTENSIVE LEDGE AND RIP-  
RAP REPAIRS  
DOWNSTREAM FROM 2017  
HEAVY RAIN EVENTS BY  
BOBM.

A466 25





**ORFORD 217/112**  
NH 25A over BRACKETT BROOK

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Friday, November 17, 2017

EAST APPROACH.

A461 51



Friday, November 17, 2017

WEST APPROACH.

A461 52



Friday, November 17, 2017

DOWNSTREAM ELEVATION.

A461 57





**ORFORD 217/112**  
**NH 25A over BRACKETT BROOK**

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Friday, November 17, 2017

VIEW OF UPSTREAM  
CHANNEL RELINED WITH  
LEDGE EROSION STONE BY  
BOBM.

A461 53



Friday, November 17, 2017

UPSTREAM VIEW OF  
GRAVEL DEBRIS REMOVED  
FROM WEST AND EAST  
BARRELS BY BOBM; 6' 6"  
OPENING AT UPSTREAM  
WEST BARREL AND 7' 4"  
OPENING AT UPSTREAM  
EAST BARREL.

A461 54



Friday, November 17, 2017

VOIDS IN SE STONE WING  
EXTENSION REPAIRED BY  
BOBM; APPEARS  
EXTENSION WASHED OUT  
DURING OCTOBER FLOOD.

A461 55



**ORFORD 217/112**  
NH 25A over BRACKETT BROOK

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Friday, November 17, 2017

VIEW FROM DOWNSTREAM  
OF DEBRIS REMOVED  
FROM BARRELS BY BOBM;  
1' OF FOOTING FACE  
EXPOSED AT PIER  
EXTENSION DOWNSTREAM.

A461 56





**ORFORD 217/112**  
NH 25A over BRACKETT BROOK

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Thursday, March 30, 2017

FEW POTHOLES IN  
PAVEMENT; FOG LINE  
EASTBOUND LANE AND  
EAST SLAB END EAST  
BOUND LANE.

A442 12



**ORFORD 217/112**  
**NH 25A over BRACKETT BROOK**

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Monday, November 07, 2016

MISSING STONES, LARGE  
VOIDS AND SETTLED  
UPSTREAM SE STONE  
RETAINING WALL.

A438 61



Monday, November 07, 2016

MISSING STONES, LARGE  
VOIDS AND SETTLED  
UPSTREAM SE STONE  
RETAINING WALL.

A438 62



Monday, November 07, 2016

MODERATE TO HEAVY  
EFFLORESCENCE AND  
RUST STAINS IN THE WEST  
PIER FACE; TYPICAL.

A438 63





**ORFORD 217/112**  
NH 25A over BRACKETT BROOK

Owner: NHDOT  
Inspection Team: A  
Bridge Maintenance Crew: 10

Wednesday, March 23, 2016

WEST END SLAB ASPHALT  
CRACKED AND BREAKING  
UP; ROADWAY ASPHALT  
POTHOLED.

A416 46



Wednesday, March 23, 2016

3" SETTLEMENT IN SE  
STONE RETAINING WALL.

A416 47

